



Mex Material Handling Norte S.A. de C.V.
 Calle de Los Mayos #13 Col. Parque Industrial
 Hermosillo, Sonora, Mexico C.P. 83299

Condition Report - M581

Description	CLASE V	Tire	Solida neumatica
Make	NISSAN	Mast Stage	Three Stage Free Lift
Model	MAP1F1A18LV	Mast Collapsed	82"
Drive Hours	3753	Mast Elevated	187"
Fuel	Combustion a gas	Hydraulic	3 - WAY LEVER
Fork Lengh	48"	Attachment	SIDE SHIFTER



Category	Description	Status	Action	Comments
Attachments/Fork	Condition	Good		
Upright	Chains	Good		
	Mast	Good		
Tilt Cylinder(s)	Tilt Cylinder(s)	Good		
Lift Cylinder(s)	Lift Cylinder(s)	Good		
Pump / Motor	Hoses	Good		
	Levers	Good		
	Pump / Motor	Good		
Carriage	Frame	Good		
	Rollers	Good		
Load Back Rest	Load Back Rest	Good		
Drive Axle	Drive Axle	Good		
Drive Gear(s)	Drive Gear(s)	Good		
	Drive Motor	Good		
Steer Axle	Steer Axle	Good		
Brakes	Parking Brake	Good		
	System	Good		
Covers	Covers	Good		
	Dash	Good		
	Fenders	Good		
	Hood	Good		
	Overall	Good		
Appearance	Frame	Good		
Frame	Drive Tire %			
	Remaining	100%		
Tires	Drive Tires	Good		
	Steer Tire %			
	Remaining	100%		
	Steer Tires	Good		
	Cushions / Seat Belt	Good		
Seat	Head Lights	Good		
Lights	Strobe Light	Good		
	Alarms & Horn	Good		
Safety	Mirrors	Good		
	Overhead Guard	Good		
	Pedals & Floor Mat	Good		